

2-11-15

(b) (6), (b) (7) called at approx 10:17 one of the farm labor had seen (b) (6), (b) (7) looking at 2 bridges on Litton Road around her house. Litton road has 2 bridges out and no thru traffic from HWY 61 to Herbison Road. We had a trail cam on Litton Road just East of Herbison. (b) (6), (b) (7) was on this bridge at 10:17AM. We have repaired a line on this bridge two times already.

2-12-15

At approx 4:24PM (b) (6), (b) (7)(C) saw (b) (6) on turn row at a bridge on Hwy 448. Approx 5:00 (b) (6), (b) (7)(C) hear loud noise and had no water. We looked for leak from 5:00PM to 11:30PM did not find leak. 2-14-15 Found shot line on Dixon Road at same location that was shot before. (b) (6), (b) (7) was on scene for Bolivar SO case number 2015020044. Parts used 60 ft 4" pipe 2 4" knock on.